

EASA
Safety Recommendation Reply

Recommendation NETH-2011-015 received on 16/12/2011

Subject:	Serious incident to Boeing 737, registration PH-BPD, on 10/02/2010, at Schiphol Airport, The Netherlands
Safety Recommendation:	The DSB recommends to both EASA and FAA that the minimum CVR recording time should be increased to support safety investigations.
Response:	EASA acknowledges receipt of this Safety Recommendation. Please be advised that it is under consideration and that the outcome will be communicated to you in due course.